



June 14, 1994

Mr. Robert S. Dinwiddie  
Hazardous and Radioactive Materials Bureau  
State of New Mexico Environment Department  
525 Camino de los Marquez, P.O. Box 26110  
Santa Fe, NM 87502

RE: Safety Kleen Corp. Albuquerque, NM EPA #NMD000804294

Dear Stu:

I am requesting a modification to the above listed permit for Albuquerque, NM. The modification required should show that the Albuquerque facility of Safety Kleen Corp. has only two (2) underground storage tanks (USTs). The permit states that there are three USTs, however, our records show that there are only two.

We have discussed this on previous occasions and there seemed to be some confusion on whether or not there was indeed a third UST. The contractor who performed the removal of old USTs and the installation of the current USTs (Tri-hydro Corp.) has assured me that a search was performed for the third UST and it did not exist at the time of installation. Safety Kleen has not installed any other tanks and therefore we can find no evidence of a third UST having ever been, or currently, in use at this facility.

At this time I am requesting your assistance in the next step toward modification of our permit. If you have any comments or questions please contact me at (505) 884-0260.  
Thank you.

Sincerely,

Darla Jo Huff  
Senior Environmental Engineer  
Safety Kleen Corp.

cc: Rich Meyer - EPA Region VI