



Department of Energy
National Nuclear Security Administration
Sandia Field Office
P.O. Box 5400
Albuquerque, NM 87185



JUL 27 2016

CERTIFIED MAIL-RETURN RECEIPT REQUESTED

Mr. John E. Kieling
Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Bldg. 1
Santa Fe, New Mexico 87505

JUL 29 2016

Hazardous Waste Bureau

Subject: Department of Energy/National Nuclear Security Administration Sandia National Laboratories Environmental Restoration Operations Consolidated Quarterly Report, July 2016

Dear Mr. Kieling:

Enclosed is the Environmental Restoration Operations Consolidated Quarterly Report (ER Quarterly Report), July 2016, for the Department of Energy/National Nuclear Security Administration (DOE/NNSA), Sandia National Laboratories/New Mexico (SNL/NM), Environmental Protection Agency identification number NM5890110518. This report addresses all quarterly reporting (January 2016 through March 2016) required under the Compliance Order on Consent (Consent Order) dated April 2004, between the DOE, Sandia Corporation (Sandia), and the New Mexico Environment Department (NMED).

The DOE and Sandia have received the NMED letter dated May 20, 2016 and appreciate NMED's clarification of information presented in Section 2.3 (ER Operations Documents Submitted to the NMED Pending Regulatory Review and Approval). Updates to Section 2.3 that are related to correspondence received during the current reporting period (January 2016 through March 2016) have been incorporated in the enclosed Quarterly Report. Updates to Section 2.3 that are based solely on information provided in the May 20, 2016 letter will be incorporated in the next Quarterly Report for April through June.

If you have questions, please contact me at (505) 284-6668 or David Rast of our staff at (505) 845-5349.

Sincerely,

James Todd
Assistant Manager for Engineering

cc: See Page 2

cc w/enclosure (Certified Mail):

Brian Salem, NMED-HWB

121 Tijeras Avenue, NE, Albuquerque, NM 87102-3400

Laurie King, EPA, Region 6

1445 Ross Ave., Ste. 1200

Dallas, TX 75202

Susan Lucas-Kamat, NMED-OB

Zimmerman Library, UNM

MSC05 3020

1 University of New Mexico, Albuquerque, NM 87101-0001

cc w/o enclosure:

Amy Blumberg, SNL/NM

John Cochran, SNL/NM

Peter Davies SNL/NM

David Miller, SNL/NM

M. Anna Gallegos, SNL/NM

Howard Huie, DOE/EM-31

Douglas Tonkay, DOE/EM-31

Steve Black, NNSA/NA-533

Tom Longo, NNSA/NA-533

Jessica Arcidiacono, NNSA/NA-533

David Rast, SFO/ENG

Joe Estrada, SFO/ENG

Karen Oden, SFO/ENG

Cynthia Wimberly, SFO/OOM

687193

CERTIFICATION STATEMENT FOR APPROVAL AND FINAL RELEASE OF DOCUMENTS

Document Title: Environmental Restoration Operations Consolidated
Quarterly Report, July, 2016

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision according to a system designed to ensure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine or imprisonment for knowing violations.



Signature

Peter Davies, Director
Geoscience, Climate, and Consequence Effects
Center 6900
Sandia National Laboratories/New Mexico
Albuquerque, New Mexico 87185
Operator
and

7/12/16

Date



Signature

James Todd
U.S. Department of Energy
National Nuclear Security Administration
Sandia Field Office
Owner and Co-Operator

26 July 2016

Date

Sandia National Laboratories, New Mexico

Environmental Restoration Operations

A U.S. Department of Energy Environmental Cleanup Program

Consolidated Quarterly Report

January – March 2016



July 2016



United States Department of Energy
Sandia Field Office

CONSOLIDATED QUARTERLY REPORT

July 2016

SANDIA NATIONAL LABORATORIES, NEW MEXICO

ENVIRONMENTAL RESTORATION OPERATIONS

U.S. DEPARTMENT OF ENERGY:
CONTRACTOR:
PROJECT MANAGER:

SANDIA FIELD OFFICE
SANDIA CORPORATION
John R. Cochran

**NUMBER OF POTENTIAL RELEASE SITES SUBJECT TO RESOURCE
CONSERVATION AND RECOVERY ACT FACILITY OPERATING PERMIT, AND THE
COMPLIANCE ORDER ON CONSENT: 13**

SUSPECT WASTE: Radionuclides, metals, organic compounds, and explosives

REPORTING PERIOD: January – March 2016

OVERVIEW

This Sandia National Laboratories, New Mexico Environmental Restoration Operations (ER) Consolidated Quarterly Report (ER Quarterly Report) fulfills all quarterly reporting requirements set forth in the Resource Conservation and Recovery Act Facility Operating Permit, and the Compliance Order on Consent. The 13 sites in the corrective action process are listed in Table I-1. This ER Quarterly Report presents activities and data in sections as follows:

SECTION I: Environmental Restoration Operations Consolidated Quarterly Report,
January – March 2016

Semiannual sampling at the Burn Site Groundwater Area of Concern currently includes perchlorate analyses at one groundwater monitoring well. Due to the semiannual nature of the sampling, no groundwater samples were collected for perchlorate analyses during this reporting period. Therefore, this edition of the ER Quarterly Report does not include Section II “*Perchlorate Screening Quarterly Groundwater Monitoring Report.*”

ABBREVIATIONS AND ACRONYMS

µg/L	microgram(s) per liter
AGMR	Annual Groundwater Monitoring Report
ALTMM	Annual Long-Term Monitoring and Maintenance
AOC	Area of Concern
AVN	Area V (North)
BSG	Burn Site Groundwater
BW	background well
CAC	corrective action complete
CCBA	Coyote Canyon Blast Area
CTF	Coyote Test Field
CWL	Chemical Waste Landfill
CY	Calendar Year
CYN	Canyons (Burn Site Groundwater Area of Concern)
DOE	U.S. Department of Energy
EPA	U.S. Environmental Protection Agency
ER	Environmental Restoration Operations
ER Quarterly Report	Environmental Restoration Operations (ER) Consolidated Quarterly Report
HWB	Hazardous Waste Bureau
ISB	in situ bioremediation
LWDS	liquid waste disposal system
MCL	maximum contaminant level
MW	monitoring well
MWL	Mixed Waste Landfill
NA	not applicable
NMED	New Mexico Environment Department
NNSA	National Nuclear Security Administration
OIG	Office of Inspector General
PCCP	Post-Closure Care Permit
Permit	RCRA Facility Operating Permit
PGS	Parade Ground South
RCRA	Resource Conservation and Recovery Act
Sandia	Sandia Corporation
SNL/NM	Sandia National Laboratories, New Mexico
SWMU	Solid Waste Management Unit
TA	Technical Area
TA1-W	Technical Area I (Well)
TA2-NW	Technical Area II (Northwest)
TA2-SW	Technical Area II (Southwest)

TA2-W	Technical Area II (Well)
TAVG	Technical Area-V Groundwater
TAG	Tijeras Arroyo Groundwater
TAV	Technical Area V (acronym used in tables only)
TA-V	Technical Area V
TCE	trichloroethene
TJA	Tijeras Arroyo
TSWP	Treatability Study Work Plan
WYO	Wyoming
VCA	Voluntary Corrective Action

SECTION I
TABLE OF CONTENTS

ENVIRONMENTAL RESTORATION OPERATIONS CONSOLIDATED QUARTERLY

	REPORT, January – March 2016.....	I-1
1.0	Introduction	I-1
2.0	Environmental Restoration Operations Work Completed.....	I-1
2.1	Sites Undergoing Corrective Action	I-1
2.1.1	Solid Waste Management Units 8 and 58, 68, 149, and 154	I-2
2.1.2	Solid Waste Management Unit 502	I-2
2.1.3	Burn Site Groundwater Area of Concern	I-2
2.1.4	Technical Area-V Groundwater Area of Concern	I-3
2.1.5	Tijeras Arroyo Groundwater Area of Concern.....	I-4
2.2	Sites in Corrective Action Complete Regulatory Process.....	I-5
2.2.1	Mixed Waste Landfill.....	I-5
2.3	Environmental Restoration Operations Documents Submitted to the New Mexico Environment Department Pending Regulatory Review and Approval	I-6
3.0	References	I-7

LIST OF TABLES

Table	Title
I-1	Solid Waste Management Units and Areas of Concern Where Corrective Action Is Not Complete
I-2	Groundwater Sampling and Analysis

This page intentionally left blank.

SECTION I

ENVIRONMENTAL RESTORATION OPERATIONS CONSOLIDATED QUARTERLY REPORT, January – March 2016

1.0 Introduction

This Environmental Restoration Operations Consolidated Quarterly Report (ER Quarterly Report) provides the status of ongoing corrective action activities being implemented by Sandia National Laboratories, New Mexico (SNL/NM) for the January, February, and March 2016 quarterly reporting period.

The Solid Waste Management Units (SWMUs) and Areas of Concern (AOCs) identified for corrective action at SNL/NM are listed in Table I-1. The work completed during this quarter is reported below in Sections I.2.1 and I.2.2. Section I.2.1 summarizes the quarterly activities at sites undergoing corrective action *field* activities (SWMUs 8 and 58, 68, 149, 154, and 502, and three groundwater AOCs). Section I.2.2 summarizes quarterly activities at sites where the New Mexico Environment Department (NMED) has issued a certificate of completion and the sites are in the corrective action complete (CAC) *regulatory* process. Currently, the Mixed Waste Landfill (MWL, SWMU 76) is the only site in the CAC regulatory process.

Corrective action activities have been deferred at the Long Sled Track (SWMU 83), the Gun Facilities (SWMU 84), and the Short Sled Track (SWMU 240) because these three sites are active mission facilities. These three sites are located in Technical Area (TA)- III.

2.0 Environmental Restoration Operations Work Completed

2.1 Sites Undergoing Corrective Action

In a letter dated March 30, 2016, the Permittees proposed a set of milestones to the NMED for delivering documents demonstrating progress towards completion of groundwater remediation at the TA-V Groundwater (TAVG), Burn Site Groundwater (BSG) and Tijeras Area Groundwater (TAG) AOCs (DOE March 2016a).

2.1.1 **Solid Waste Management Units 8 and 58, 68, 149, and 154**

In February 2015, NMED agreed that corrective action activities at SWMUs 8 and 58, 68, 149, and 154 had been completed, and that certificates of completion could be requested (NMED February 2015). A letter requesting Certificates of Completion for these SWMUs was submitted to NMED on September 9, 2015 (DOE September 2015). In January 2016, NMED granted the Certificates of Completion for these SWMUs (NMED January 2016a).

2.1.2 **Solid Waste Management Unit 502**

The U.S. Department of Energy/National Nuclear Security Administration (DOE/NNSA) and Sandia Corporation (Sandia) formally notified the NMED of this newly identified or suspected SWMU by letter dated December 19, 2012 (DOE December 2012). A January 2013 inspection of the discharge area, with assistance from personnel associated with the processes that generated the wastewater, identified several small zones of discolored soil within a total area approximately 10 feet wide by 25 feet long. Subsequent actions are described in the ER Consolidated Quarterly Report, July – September 2015 (SNL/NM January 2016).

On June 7, 2013, the DOE/NNSA and Sandia submitted a Voluntary Corrective Action (VCA) Plan to NMED (DOE June 2013). On July 23, 2013, field activities were completed in accordance with the VCA Plan.

Results of the VCA were reported to the NMED under a cover letter dated November 12, 2013 (DOE November 2013). DOE/NNSA and Sandia recommended a determination of CAC without controls for SWMU 502, based upon the field investigation results, soil sample analytical data, and the human health and ecological risk assessments. On February 29, 2016, the NMED approved the November 2013 VCA Report and noted that the DOE and Sandia may request a permit modification for CAC status for SWMU 502 (NMED February 2016a).

2.1.3 **Burn Site Groundwater Area of Concern**

The DOE/NNSA and Sandia met with the NMED Hazardous Waste Bureau (HWB) on July 20, 2015 to discuss the status of sites currently undergoing corrective action. For the BSG AOC, all parties agreed to a weight-of-evidence characterization program: (1) to conduct additional isotopic analyses/nitrate fingerprinting and age-dating of the groundwater; (2) to conduct a transducer study using existing wells to determine if the

groundwater is unconfined, semi-confined, or confined; and (3) to conduct a detailed aquifer pumping test to help determine the origin of the elevated nitrates in the groundwater. Activities (1) and (2) will be completed using Sandia-internal work plans. For activity (3), the Aquifer Pumping Test Work Plan for the BSG AOC will be transmitted to the NMED in June 2016 for review and approval.

Semiannual sampling at the BSG AOC currently includes perchlorate analyses at one groundwater monitoring well. Due to the semiannual nature of the sampling, no groundwater samples were collected for perchlorate analysis during this reporting period. Therefore, this edition of the ER Quarterly does not include Section II “*Perchlorate Screening Quarterly Groundwater Monitoring Report.*”

The following activities occurred at BSG AOC during January, February, and March 2016:

- For the vertical profiling survey that was conducted at the Burn Site Well and CYN-MW11 in December 2015, a technical memorandum was prepared for internal review. The memorandum is anticipated to be finalized in the next quarter.
- The DOE/NNSA and Sandia met with the NMED HWB on February 19, 2016 to further discuss the status and schedule of the BSG AOC weight-of-evidence characterization program.
- The Long Term Transducer study was implemented with water level data collected in all BSG AOC wells from January 11, 2016 through March 13, 2016.

2.1.4 **Technical Area-V Groundwater Area of Concern**

Trichloroethene (TCE) and nitrate have been identified as constituents of concern in groundwater at the TAVG AOC based on detections above the U.S. Environmental Protection Agency (EPA) maximum contaminant levels (MCLs) in samples collected from monitoring wells. The EPA MCLs and State of New Mexico drinking water standards for TCE and nitrate are 5 micrograms per liter ($\mu\text{g/L}$) and 10 milligrams per liter (as nitrogen), respectively.

Personnel from the DOE/NNSA, DOE Headquarters Office of Environmental Management, Sandia, and NMED worked together to address the groundwater contamination at TAVG AOC. A meeting was held at the NMED HWB on July 20, 2015, and all parties agreed on a phased Treatability Study for in-situ bioremediation (ISB) to treat the groundwater contamination at TAVG AOC.

For the Treatability Study, up to three injection wells will be installed at TA-V in the vicinity of the highest contaminant concentrations in groundwater detected in monitoring wells LWDS-MW1, TAV-MW6, and TAV-MW10. The proposed injection wells will be used to deliver substrate solution and bioaugmentation bacteria to groundwater. The substrate solution containing essential food and nutrients for biostimulation will be prepared in aboveground tanks. The substrate solution will be gravity-injected along with the bioaugmentation bacteria to groundwater via injection wells. The overall objective is to assess the feasibility of using ISB to remediate groundwater contamination at TA-V.

The following activities occurred at TAVG AOC during January, February, and March 2016:

- DOE/NNSA and Sandia requested an extension to submit the revised Treatability Study Work Plan (TSWP) and the response letter to NMED's comments on the initial version of the TSWP on January 15, 2016 (DOE January 2016). NMED approved the extension request on January 29, 2016 (NMED January 2016b). The new due date for submittal of the revised TSWP is March 31, 2016.
- DOE/NNSA and Sandia revised the TSWP based on NMED's comments on the initial version of the TSWP (NMED December 2015). The revised TSWP and the response letter (SNL/NM March 2016) were submitted to NMED in March 2016 (DOE March 2016b).
- DOE/NNSA and Sandia are working on Notice of Intent to Discharge for the Treatability Study injection wells per the requirements of NMED Ground Water Quality Bureau.
- Groundwater sampling was conducted in February and March 2016. The well identification and the frequency that these wells were sampled are presented in Table I-2. The analytical results for groundwater monitoring will be presented in the SNL/NM calendar year (CY) 2016 Annual Groundwater Monitoring Report, which is anticipated to be submitted to the NMED in the summer of 2017.

2.1.5 **Tijeras Arroyo Groundwater Area of Concern**

Groundwater sampling at the TAG AOC was conducted in March 2016. The well identification and the frequency that these wells were sampled are presented in Table I-2. The analytical results for groundwater monitoring will be presented in the SNL/NM CY 2016 Annual Groundwater Monitoring Report, which is anticipated to be submitted to the NMED in the summer of 2017.

Preparation of two TAG reports (the Current Conceptual Model and the Corrective Measures Evaluation Report) began this quarter. Submittal of the two reports to NMED HWB is scheduled for December, 2016.

2.2 **Sites in Corrective Action Complete Regulatory Process**

After NMED certifies completion of corrective action activities at a SWMU or an AOC, a Class 3 Permit Modification to the Resource Conservation and Recovery Act (RCRA) Facility Operating Permit (Permit) is requested to formally change the status of the SWMU or AOC from Corrective Action Required to either CAC without Controls or CAC with Controls. The Class 3 Permit Modification process is a regulatory process. Currently, the MWL is the only site in the CAC regulatory process.

2.2.1 **Mixed Waste Landfill**

The NMED issued the Certificate of Completion for the MWL on October 8, 2014 (NMED October 2014). The DOE/NNSA and Sandia subsequently submitted a Class 3 Permit Modification Request to NMED to change the MWL status to CAC with Controls on October 17, 2014 (DOE October 2014). The request and associated legal notice initiated the DOE/NNSA and Sandia 60-day public comment period that was completed on January 5, 2015, and included a public meeting that was held on November 18, 2014. NMED issued a public notice announcing their intent to approve the DOE/NNSA and Sandia request for CAC with controls status for the MWL and initiated a 60-day public comment period that started on January 12, 2015 (NMED January 2015). On March 17, 2015, NMED extended this public comment period an additional 30 days, to April 13, 2015. On April 29 and May 4, 2015, NMED conducted informal negotiations open to all parties that requested a hearing during the public comment period. These meetings did not resolve identified issues to the satisfaction of all parties that requested a hearing, so the NMED proceeded with a public hearing from July 8 through 11, 2015. During the hearing, Sandia staff provided direct and rebuttal testimony, as well as being subjected to cross-examination. The Hearing Officer's Report was issued on October 13, 2015 recommending CAC with controls status be granted for the MWL.

On February 12, 2016, the NMED Secretary Ryan Flynn issued the Final Order *In the Matter of Proposed Permit Modification for Sandia National Laboratories EPA ID No. NM5890110518 to Determine Corrective Action Complete with Controls at the Mixed Waste Landfill*, No. HWB 15-18 (P) (NMED February 2016b). The Class 3 Permit Modification for MWL CAC with Controls was approved by NMED on February 18, 2016

(NMED February 2016c). As of March 13, 2016, the February 2016 Final Order became effective, granting the Class 3 Permit Modification to reflect that the MWL is CAC with Controls.

Ongoing long-term monitoring, inspection, maintenance/repair, and reporting activities are conducted by the SNL/NM Long-Term Stewardship Program and are documented in MWL Annual Long-Term Monitoring and Maintenance Reports submitted to the NMED in June of each year.

The DOE Office of Inspector General (OIG) special investigation of the MWL that was initiated by requests to their hotline in late 2014 and early 2015 was completed on February 18, 2016 with issuance of their *Special Report, Allegations Regarding the Sandia National Laboratories Mixed Waste Landfill* (DOE OIG February 2016). The OIG Report substantiated one of the six allegations investigated: that the inventory of the MWL is not complete. The DOE OIG acknowledged that this issue was previously addressed at the December 2004 public hearing for final remedy selection. The DOE OIG was not able to substantiate the other five allegations during their one-year plus investigation, and they concluded that DOE/NNSA and Sandia should continue to comply with long-term monitoring, inspection, and reporting requirements of the May 2005 NMED Final Order (NMED May 2005).

2.3 **Environmental Restoration Operations Documents Submitted to the New Mexico Environment Department Pending Regulatory Review and Approval**

This section lists ER documents that have been submitted to the NMED and are, as of this reporting period, still pending review and approval:

- The BSG Interim Measures Work Plan submitted to the NMED on May 26, 2005 (SNL/NM May 2005).
- The BSG Current Conceptual Model of Groundwater Flow and Contaminant Transport submitted to the NMED on April 9, 2008 (SNL/NM March 2008).
- The TA-V Geophysical Logs and Slug Test Results Report submitted to the NMED on November 24, 2010 (SNL/NM November 2010).

- The Revised TWSP for In-Situ Bioremediation at the TAVG AOC submitted to the NMED on March 18, 2016 (SNL/NM March 2016).
- The MWL Groundwater Monitoring Report for CY 2010 submitted to the NMED on September 30, 2011 (SNL/NM September 2011).

3.0 **References**

New Mexico Environment Department (NMED), May 2005. “Final Order, State of New Mexico Before the Secretary of the Environment in the Matter of Request for a Class 3 Permit Modification for Corrective Measures for the Mixed Waste Landfill, Sandia National Laboratories, Bernalillo County, New Mexico, EPA ID#5890110518, No. HWB 04-11(M),” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, May 26, 2005.

New Mexico Environment Department (NMED), October 2014. Letter to G. Beausoleil (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Certificate of Completion for the Mixed Waste Landfill, September 25, 2014, Sandia National Laboratories, EPA ID# NM5890110518, HWB-SNL-14-MISC,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, October 8, 2014.

New Mexico Environment Department (NMED), January 2015. Letter to G. Beausoleil (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Notice of Public Comment Period for Proposed Determination of Corrective Action Complete with Controls for Sandia National Laboratories Mixed Waste Landfill, Sandia National Laboratories, EPA ID# NM5890110518, HWB-SNL-14-014,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, January 12, 2015.

New Mexico Environment Department (NMED), February 2015. Letter to G. Beausoleil (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Approval Annual Groundwater Monitoring Report, Calendar Year 2013, June 2014, Sandia National Laboratories, EPA ID# NM5890110518, HWB SNL 14 013,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, February 4, 2015.

New Mexico Environment Department (NMED), December 2015. Letter to J. Harrell (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Disapproval Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern, September 2015, Sandia National Laboratories, EPA ID# NM5890110518, HWB-SNL-15-020,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, December 3, 2015.

New Mexico Environment Department (NMED), January 2016a. Letter to J. Harrell (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Certificates of Completion for the Solid Waste Management Units 68, 149, 154, 8 and 58, September 2015, Sandia National Laboratories, EPA ID# NM5890110518, HWB-SNL-15-018,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, January 19, 2016.

New Mexico Environment Department (NMED), January 2016b. Letter to J. Harrell (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Approval Request for Extension for Submittal of Revised Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern and Response to the Notice of Disapproval dated December 3, 2015, Sandia National Laboratories, EPA ID# NM5890110518, HWB-SNL-15-020,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, January 29, 2016.

New Mexico Environment Department (NMED), February 2016a. Letter to J. Harrell (U.S. Department of Energy NNSA/Sandia Field Office) and P. Davies (Sandia National Laboratories, New Mexico), “Approval Investigation Report for Voluntary Correction Action at Solid Waste Management Unit 502 Building 9938 Surface Discharge Site for Sandia National Laboratories/New Mexico, October 2013, Sandia National Laboratories EPA ID# NM5890110518, SNL-15-013,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, February 29, 2016.

New Mexico Environment Department (NMED), February 2016b. “*Final Order, State of New Mexico Before the Secretary of the Environment in the Matter of Proposed Permit Modification for Sandia National Laboratories, EPA ID# 5890110518, To Determine Corrective Action Complete with Controls at the Mixed Waste Landfill, No. HWB 15-18(P)*,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, February 12, 2016.

New Mexico Environment Department (NMED), February 2016c. Letter to J.P. Harrell (U.S. Department of Energy, NNSA/Sandia Field Office) and P.B. Davies (Sandia National Laboratories, New Mexico), “Approval Final Decision on Proposal to Grant Corrective Action Complete with Controls Status for Mixed Waste Landfill, Sandia National Laboratories, EPA ID# NM5890110518, HWB-SNL-14-014,” NMED, Hazardous Waste Bureau, Santa Fe, New Mexico, February 18, 2016.

NMED, see New Mexico Environment Department.

Sandia National Laboratories, New Mexico (SNL/NM), May 2005. “Burn Site Groundwater Interim Measures Work Plan,” Sandia National Laboratories, Albuquerque, New Mexico.

Sandia National Laboratories, New Mexico (SNL/NM), March 2008. “Current Conceptual Model of Groundwater Flow and Contaminant Transport at Sandia National Laboratories/New Mexico Burn Site,” Sandia National Laboratories, Albuquerque, New Mexico.

Sandia National Laboratories, New Mexico (SNL/NM), November 2010. “Technical Area-V Geophysical Logs and Slug Test Results,” Sandia National Laboratories, Albuquerque, New Mexico.

Sandia National Laboratories, New Mexico (SNL/NM), September 2011. “Mixed Waste Landfill Groundwater Monitoring Report, Calendar Year 2010,” Sandia National Laboratories, Albuquerque, New Mexico.

Sandia National Laboratories, New Mexico (SNL/NM), January 2016. “Consolidated Quarterly Report, July – September 2015,” Sandia National Laboratories, Albuquerque, New Mexico.

Sandia National Laboratories, New Mexico (SNL/NM), March 2016. “Response to NMED Disapproval Letter, HWB-SNL-15-020, Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern, September 2015, Sandia National Laboratories, EPA ID# NM5890110518, dated December 3, 2015, and Revised Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern,” Sandia National Laboratories, Albuquerque, New Mexico.

SNL/NM, see Sandia National Laboratories, New Mexico.

U.S. Department of Energy (DOE), December 2012. Letter to J. Kieling (New Mexico Environment Department), “Notification of Newly Identified or Suspected Solid Waste Management Unit/Area of Concern at Sandia National Laboratories/New Mexico,” DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, December 19, 2012.

U.S. Department of Energy (DOE), June 2013. Letter to J. Kieling (New Mexico Environment Department), “Submittal of Long Term Stewardship Voluntary Corrective Action Plan for Building 9938 Surface Discharge Site for Sandia National Laboratories/New Mexico, EPA ID# NM 5890110518,” DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, June 7, 2013.

U.S. Department of Energy (DOE), November 2013. Letter to D. Cobrain (New Mexico Environment Department), “Submittal of Investigation Report for Voluntary Corrective Action at Solid Waste Management Unit 502 Building 9938 Surface Discharge Site for Sandia National Laboratories/New Mexico, EPA ID# NM5890110518,” November 2013.

U.S. Department of Energy (DOE), October 2014. Letter to J.E. Kieling (New Mexico Environment Department), “Request for Class 3 Modification to Module IV of Hazardous Waste Permit for Sandia National Laboratories/New Mexico, EPA ID# NM5890110518, New Mexico,” DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, October 17, 2014.

U.S. Department of Energy (DOE), September 2015. Letter to J.E. Keiling (New Mexico Environment Department), “Request for Certificates of Completion from the New Mexico Environment Department for Solid Waste Management Units (SWMUs) 68 and 149 (without controls) and SWMUs 154, 8, and 58 (with controls),” EPA ID# NM5890110518, DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, September 4, 2015.

U.S. Department of Energy (DOE), January 2016. Letter to J.E. Keiling (New Mexico Environment Department), “Request for Extension for Submittal of Revised Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern and Response to the Notice of Disapproval dated December 3, 2015,” DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, January 15, 2016.

U.S. Department of Energy (DOE), March 2016a. Letter to J.E. Keiling (New Mexico Environment Department), “Summary of Agreements and Proposed Milestones Pursuant to the Meeting of July 20, 2015,” DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, March 30, 2016.

U.S. Department of Energy (DOE), March 2016b. Letter to J.E. Keiling (New Mexico Environment Department), “Response to NMED Disapproval Letter, HWB-SNL-15-020, Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern, September 2015, Sandia National Laboratories, EPA ID NM5890110518, dated December 3, 2015, and Revised Treatability Study Work Plan for In-Situ Bioremediation at the Technical Area-V Groundwater Area of Concern,” DOE, National Nuclear Security Administration, Sandia Field Office, Albuquerque, New Mexico, March 18, 2016.

U.S. Department of Energy, Office of Inspector General (DOE OIG), February 2016. “Special Report, Allegations Regarding the Sandia National Laboratories Mixed Waste Landfill.” DOE, Office of Inspector General, Office of Audits and Inspections, Western Audit Division, February 18, 2016.

Tables

**Table I-1
Solid Waste Management Units and Areas of Concern
Where Corrective Action Is Not Complete**

Solid Waste Management Units and Areas of Concern	
Site Number	Site Description
8	Open Dump (CCBA)
58	CCBA
68	Old Burn Site
76	MWL (TA-III)
83	Long Sled Track
84	Gun Facilities
149	Building 9930 Septic System (CTF)
154	Building 9960 Septic System and Seepage Pits (CTF)
240	Short Sled Track
NA	Tijeras Arroyo Groundwater Investigation (TAG AOC)
NA	TA-V Groundwater Investigation (TAVG AOC)
NA	Burn Site Groundwater Investigation (BSG AOC)
502	Building 9938 Surface Discharge Site
Total	13

Notes

- AOC = Area of Concern.
- BSG = Burn Site Groundwater.
- CCBA = Coyote Canyon Blast Area.
- CTF = Coyote Test Field.
- MWL = Mixed Waste Landfill.
- NA = Not applicable. A site number was not assigned.
- TA = Technical Area.
- TAG = Tijeras Arroyo Groundwater.
- TA-V = Technical Area-V.
- TAVG = Technical Area-V Groundwater.

**Table I-2
Groundwater Sampling and Analysis**

Investigation Site	Sampling Frequency in CY 2016 ^a	Quarter of Sampling in CY 2016	Location of Analytical Results	Location of Perchlorate Analytical Results	Monitoring Wells in Network
TAVG AOC	Quarterly	1,2,3,4	AGMR	NA	AVN-1, LWDS-MW1, LWDS-MW2, TAV-MW2, TAV-MW3, TAV-MW4, TAV-MW5, TAV-MW6, TAV-MW7, TAV-MW8, TAV-MW9, TAV-MW10, TAV-MW11, TAV-MW12, TAV-MW13, TAV-MW14
BSG AOC	Semiannually	2,4	AGMR	NA	CYN-MW4, CYN-MW7, CYN-MW8, CYN-MW9, CYN-MW10, CYN-MW11, CYN-MW12, CYN-MW13, CYN-MW14A, CYN-MW15
TAG AOC	Quarterly	1,2,3,4	AGMR	NA	PGS-2, TA1-W-01, TA1-W-02, TA1-W-03, TA1-W-04, TA1-W-05, TA1-W-06, TA1-W-08, TA2-NW1-595, TA2-W-01, TA2-W-19, TA2-W-26, TA2-W-27, TA2-W-28, TJA-2, TJA-3, TJA-4, TJA-6, TJA-7, WYO-3, WYO-4
MWL Groundwater	Semiannually	2,4	AGMR, Section 4 of MWL ALTMM Report	NA	MWL-BW2, MWL-MW7, MWL-MW8, MWL-MW9
CWL Groundwater	Semiannually	1,3	AGMR, Section 4 CWL PCCP Report	NA	CWL-BW5, CWL-MW9, CWL-MW10, CWL-MW11

Notes

^aNot all wells in a particular investigation are sampled at the same frequency; this represents the maximum frequency of sampling at a site.

- AGMR = Annual Groundwater Monitoring Report.
- ALTMM = Annual Long-Term Monitoring and Maintenance.
- AOC = Area of Concern.
- AVN = Area V (North).
- BSG = Burn Site Groundwater (Area of Concern).
- BW = Background well.
- CWL = Chemical Waste Landfill.
- CY = Calendar Year.
- CYN = Lurance Canyon.
- LWDS = Liquid Waste Disposal System.
- MW = Monitoring Well.
- MWL = Mixed Waste Landfill.
- NA = Not applicable. No wells in the site network are currently being sampled and analyzed for perchlorate.
- PCCP = Post-Closure Care Permit.
- PGS = Parade Ground South.
- TA1-W = Technical Area-I (Well).
- TA2-NW = Technical Area-II (Northwest).
- TA2-SW = Technical Area-II (Southwest).
- TA2-W = Technical Area-II (Well).
- TAG = Tijeras Arroyo Groundwater (Area of Concern).
- TAV = Technical Area-V.
- TAVG = Technical Area-V Groundwater (Area of Concern).
- TJA = Tijeras Arroyo.
- WYO = Wyoming.