

SPARTON TECHNOLOGY, INC.

4901 Rockaway Blvd., SE
Rio Rancho, New Mexico 87124
P.O. Box 1784
Albuquerque, New Mexico 87103
Phone (505) 892-5300
TWX 910-989-1657

August 17, 1987

Mr. Jack Ellvinger
Program Manager
Hazardous Waste Bureau
State of New Mexico
Environmental Improvement Division
P.O. Box 968
Santa Fe, New Mexico 87504

RECEIVED
AUG 20 1987
XIII HAZARDOUS WASTE SECTION

Dear Mr. Ellvinger:

Sparton Technology, Inc., is hereby requesting approval from EID to begin construction, testing and operation of the first phases of the ground water cleanup program at our Coors Road Plant located in Albuquerque, New Mexico. Specifically, we wish to begin installation, testing and operation of the Withdrawal Well System, the Collection System, and the Air Stripper as described in our Corrective Measure Study Report dated July 23, 1987.

Sparton proposes to perform the work in accordance with the Estimated Project Schedule contained in APPENDIX C of the Corrective Measure Study dated July 23, 1987.

It is our understanding that issuance of a Post-Closure Care Permit is estimated to take about six months. It is Sparton's desire to initiate the ground water cleanup program much sooner than that in order to affect reclamation of the aquifer in the shortest practical time.

If you have any questions, please contact Mr. Gary Richardson at (505) 828-2801.

Sincerely,



Richard D. Mico
Vice President and General Manager

cc: Mr. Blair Thompson
Mr. Jon DeWitt
Mr. Thomas Burger
Mr. Gary Richardson
Mr. Cleoves Martinez