



GARY E. JOHNSON  
GOVERNOR

State of New Mexico  
**ENVIRONMENT DEPARTMENT**  
Ground Water Protection and Remediation Bureau

Harold Runnels Building  
1190 St. Francis Drive, P.O. Box 26110  
Santa Fe, New Mexico 87502  
(505) 827-2918 phone  
(505) 827-2965 fax

MARK E. WEIDLER  
SECRETARY

EDGAR T. THORNTON, III  
DEPUTY SECRETARY

April 22, 1997

Richard D. Mico  
Vice President and General Manager  
Sparton Technology  
4901 Rockaway Blvd., SE  
Rio Rancho, NM 87124-4469

RE: Vapor Recovery Well Testing Results

Dear Mr. Mico:

Enclosed you will find copies of the SLD lab reports for the vapor samples collected from the vapor recovery wells at Sparton Technology's (Sparton) Coors Road facility on March 20, 1997. As can be seen, there is still a discrepancy between the results reported by SLD and those reported by Sparton's lab, AEN. SLD is preparing details of its quality control for these samples and I will forward this as soon as it becomes available. I will continue to work with John Wakefield to try and resolve this matter.

If you have any questions, please call me at 827-0178.

Sincerely,

  
Robert Pine  
Hydrologist  
Assessment & Abatement Section

Enclosure  
not  
Found