



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 6
1445 Ross Avenue, Suite 1200
Dallas, Texas 75202-2733



State of New Mexico
ENVIRONMENT DEPARTMENT
Hazardous Waste Bureau
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

March 29, 2013

Ernesto Martinez
Corporate EHS Manager
Sparton Technology, Inc.
30167 Power Line Road
Brooksville, FL 34602

**RE: MW-47R SOIL CUTTINGS DISPOSAL APPROVAL
SPARTON TECHNOLOGY, INC.
EPA ID NO. NMD083212332**

Dear Mr. Martinez:


The Environmental Protection Agency (EPA) and the New Mexico Environment Department (NMED) have reviewed the February 2013 Monthly Progress Report (Report), submitted by Hurst Engineering Services on behalf of Sparton Technology, Inc. (Sparton).

The Report stated that Sparton planned to empty six barrels of drill cuttings on the driveway around CW-2. Given the low contaminant concentration of TCE (1.1 microgram per liter) in the groundwater from the monitor well, EPA and NMED agree that the cuttings can be disposed of in the method proposed in the February 2013 Report.

Mr. Martinez
March 29, 2013
Page 2

If you have any questions, please contact John Kieling at 505-476-6035 or Chuck Hendrickson at 214-665-2196.

Sincerely,



John E. Kieling
Chief, Hazardous Waste Bureau
New Mexico Environment Department



Chuck Hendrickson
Project Coordinator
U.S. EPA Region 6

cc: Jerry Schoeppner, Chief, NMED GWQB
Brian Salem, NMED HWB
Bart Faris, NMED GWQB

Cary B. Wood, President, Sparton Technology, Inc.,
425 North Martingale Road, Suite 2050, Schaumburg, IL 60173

Tony Hurst, Hurst Engineering Services,
1022 Monaco Parkway, Denver, CO 80220

James B. Harris, Attorney, Thompson & Knight LLP,
1722 Routh Street, Suite 1500, Dallas, TX 75201-2533

Stavros S. Papadopoulos, S. S. Papadopoulos & Associates, Inc.
7944 Wisconsin Ave., Bethesda MD 20814-3620