



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 6
1445 Ross Avenue, Suite 1200
Dallas, Texas 75202-2733



ENTERED

State of New Mexico
ENVIRONMENT DEPARTMENT
Hazardous Waste Bureau
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

June 13, 2019

Mr. Ernesto Martinez
EHS Corporate Manager
Sparton Technology, Inc.
30167 Power Line Road
Brooksville, FL 34602

**RE: DISAPPROVAL
COMPLETION REPORT FOR MONITORING WELL MW-62 REPLACEMENT,
MARCH 2019
SPARTON TECHNOLOGY, INC.
EPA ID NO. NMD083212332
ST-19-001**

Dear Mr. Martinez:

The Environmental Protection Agency (EPA) and the New Mexico Environment Department (NMED) received the *Completion Report for Monitoring Well MW-62 Replacement, March 2019*, with cover letter dated March 25, 2019, submitted by S. S. Papadopoulos & Associates, Inc. on behalf of Sparton Technology, Inc. (Sparton) on March 29, 2019. The EPA and NMED have reviewed the Report and hereby issue this Disapproval with the following comments:

1. Installation of Replacement Monitoring Well MW-62R, p. 1

NMED Comment: Revise the Report to include the following information:

- a) Filter pack placement method and volumes (calculated and actual)
- b) Annular sealant placement method and volumes (calculated and actual)
- c) Surface sealant composition, placement, and volumes (calculated and actual)

Mr. Martinez
June 13, 2019
Page 2

- d) Well development purge volume and stabilization parameter and turbidity measurements

2. Attachment A: Boring/Well Construction Log, p. 1-4


NMED Comment: Revise the Report to include the following information on the boring log:

- a) Surveyed location coordinates
- b) Elevation above sea level

A revised Report that corrects all of the deficiencies noted in this letter must be submitted to EPA and NMED no later than **August 30, 2019**. The revised Report must be accompanied by a response letter that details where the NMED's comments were addressed and cross-references the numbered comments listed above. In addition, the Permittee must submit an electronic redline-strikeout version of the revised Report that shows where all changes were made to the Report.

If you have any questions, please contact Dave Cobrain at 505-476-6055 or Chuck Hendrickson at 214-665-2196.

Sincerely,



Dave Cobrain
Program Manager, Hazardous Waste Bureau
New Mexico Environment Department



Chuck Hendrickson
Project Coordinator
U.S. EPA Region 6

cc: John Kieling, Chief, NMED HWB
Michelle Hunter, Chief, NMED GWQB
Naomi Davidson, NMED HWB
Justin Ball, NMED GWQB
Pamela Homer, NMED GWQB

Cary B. Wood, President, Sparton Technology, Inc.,
425 North Martingale Road, Suite 2050, Schaumburg, IL 60173

Dillon Cottingham, Occam Engineers Inc.,
6100 Seagull Street NE, Suite 102B, Albuquerque, NM 87109

James B. Harris, Attorney, Thompson & Knight LLP,
1722 Routh Street, Suite 1500, Dallas, TX 75201-2533

Mr. Martinez
June 13, 2019
Page 3

Joseph G. McCormack, Senior Vice President, Chief Financial Officer,
Sparton Corporation
425 North Martingale Road, Suite 1000, Schaumburg, IL 60173

Stavros S. Papadopoulos, S. S. Papadopoulos & Associates, Inc.
7944 Wisconsin Ave., Bethesda MD 20814-3620