



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
2040 S. PACHECO
SANTA FE, NEW MEXICO 87505
(505) 827-7131



June 3, 1998

CERTIFIED MAIL
RETURN RECEIPT NO. Z-235-437-279

Mr. Bill Kendrick
Transwestern Pipeline Company
P.O. Box 1188
Houston, Texas 77251-1188

**RE: INVESTIGATION WORK PLAN
ROSWELL COMPRESSOR STATION**

Dear Mr. Kendrick:

The New Mexico Oil Conservation Division has reviewed Transwestern Pipeline Company's (TPC) March 28, 1998 "ANNUAL GROUND WATER MONITORING REPORT & PHASE IV SOIL AND GROUND WATER ASSESSMENT PLAN, ROSWELL COMPRESSOR STATION, TRANSWESTERN PIPELINE COMPANY". This document contains the results of TPC's ground water monitoring and TPC's work plan for additional investigations of the extent of soil and ground contamination related to the TPC Roswell Compressor Station.

The work plan as contained in the above referenced document is approved with the following conditions:

1. The proposed deep monitor well MW-25D will be installed at the location as shown on the attached figure.
2. The investigation report will be submitted to the OCD Santa Fe Office by September 18, 1998 with a copy provided to the OCD Artesia District Office.

Please be advised that OCD approval does not relieve TPC of liability if the investigation work plan fails to adequately determine the extent of contamination related to TPC's activities. In addition, OCD approval does not relieve TPC of responsibility for compliance with any other federal, state or local laws and regulations.

Mr. Bill Kendrick
June 3, 1998
Page 2

If you have any questions, please contact me at (505) 827-7154.

Sincerely,

A handwritten signature in black ink, appearing to read "Will Olson". The signature is written in a cursive, flowing style.

William C. Olson
Hydrologist
Environmental Bureau

xc: Tim Gum, OCD Artesia Office
Mike Matush, NM State Land Office
George Robinson, Cypress Engineering Services, Inc.
Benito Garcia, NMED Hazardous & Radioactive Materials Bureau

