



Department of Energy
Carlsbad Field Office
P. O. Box 3090
Carlsbad, New Mexico 88221

ENTERED



SEP 06 2011

Mr. John Kieling, Acting Bureau Chief
Hazardous Waste Bureau
New Mexico Environment Department
2905 Rodeo Park Drive East, Bldg. 1
Santa Fe, New Mexico 87505-6303

Subject: Transmittal of the Revised C6 Checklists for Audit A-11-12, Bettis Atomic Power Laboratory Central Characterization Project Waste Characterization Program

Dear Mr. Kieling:

This letter transmits the revised C6 Checklists for Carlsbad Field Office Audit A-11-12, and an attachment containing responses to the New Mexico Environment Department comments received by letter dated August 23, 2011.

If you have any questions concerning these revised documents, please contact Mr. Randy Unger, Director of the Office of Quality Assurance, at (575) 234-7065.

Sincerely,


Edward Ziemianski
Interim Manager

Enclosure

110903



Mr. John Kieling

-2-

SEP 06 2011

cc: w/Report Narrative

D. Garcia, CBFO	* ED
R. Unger, CBFO	ED
J.R. Stroble, CBFO	ED
G. Basabilvazo, CBFO	ED
T. Morgan, CBFO	ED
C. Fesmire, CBFO	ED
M. Navarrete, CBFO	ED
S. McCauslin, CBFO	ED
T. Hall, NMED	ED
S. Holmes, NMED	ED
P. Gomez, CTAC	ED
M. Mager, CTAC	ED

*ED denotes electronic distribution

cc: w/enclosures

WIPP Operating Record, MS: 452-09

CBFO M&RC

CBFO QA File

RESPONSES TO NMED COMMENTS ON THE
BETTIS ATOMIC POWER LABORATORY CENTRAL CHARACTERIZATION
PROJECT (BAPL/CCP) FINAL AUDIT REPORT A-11-12

1. Question 56a of the C6 Checklist states "List of any AK Sufficiency Determination requested for the waste stream". There should be a statement in the comment column that states that BAPL currently has no AK Sufficiency requests.

Response: Added "No sufficiency determinations were requested for this waste stream." to the comments section.

2. Question 184 of the C6 Checklist indicates the citation of CCP-TP-082, S. 4.1 and S. 4.2. There is no S. 4.2 in CCP-TP-082.

Response: The section reference has been changed to S. 4.1 on the revised C6-4 Checklist.