

State of New Mexico
ENVIRONMENT DEPARTMENT
Hazardous & Radioactive Materials Bureau
2044-A Galisteo Street (87505)
P.O. Box 26110
Santa Fe, New Mexico 87502



Phone (505) 827-1561
Fax (505) 827-1544

FAX COVER SHEET

Date: July 11, 1997
To: Linda Frank-Supka
Company: Westinghouse
Telephone: 505/234-8816
Fax: 505/885-4562

From: *SOZ* Steve Zappe
Number of Pages (including this cover sheet): 6

COMMENTS

Linda -

I have problems with the info on page 25 of the Final SWMU Assessment report for the H-3 mudpit. The chronology provided in the Supplemental Information provided in May provides a different story of the development of wells at this location. Here are some specifics:

Well H-3a - I find no reference to this well in the supplemental info, nothing about a "shallow well drilled to characterize the Dewey Lake."

Well H-3b - I presume this is H-3, which was later renamed H-3b1.

Well H-3c - I find no reference to this well either. If it supposed to be either H-3b2 or H-3b3, they were drilled in 1983, not 1987.

Well H-3d - information on this well appears correct.

In summary, H-3 was drilled first in 9/76, and was later renamed when two more wells (H-3b2 and H-3b3 were drilled in a cluster in 1983. H-3d was drilled 4/87 to test the Dewey Lake and 49er.

