

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Western Bloomfield Refinery
Initial C-141 Submitted
5/18/18 Form C-141
Revised April 3, 2017

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Western Refining Terminals, LLC	Contact: Kelly Robinson
Address: 50 CR 4990	Telephone No.: 505-632-4166
Facility Name: Bloomfield Terminal	Facility Type: Crude and Products Terminal
Surface Owner: Western Refining	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section 27	Township 29N	Range : 11W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------	------------	--------------	-------------	---------------	------------------	---------------	----------------	-----------------

Latitude 36.697049 Longitude -107.972494 NAD83

NATURE OF RELEASE

Type of Release: Crude Oil/Water/Product Mixture	Volume of Release 7 bbls hydrocarbons	Volume Recovered: All standing liquids were recovered.
Source of Release: Crack in the slop line located adjacent/north of county road 4990	Date and Hour of Occurrence: 5/17/2018	Date and Hour of Discovery 5/17/2018 at approximately 6:15am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? 5/18/2018 to Carl Chavez – NMOCD Santa FE, Vanessa Field- NMOCD, Cory Smith – NMOCD, Leona Tsinnajinnie – NMED-HWB	
By Whom? Kelly Robinson	Date and Hour 5/18/2018 at 3:09pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
On Thursday, May 17th, the Bloomfield Terminal identified a leak in an underground pipeline used to transfer water/crude/finished product mixtures from the Terminal Loading/Unloading areas on the south side of County Road 4990 to the on-site Wastewater Treatment System located north of County Road 4990. The leak originated from a crack in the elbow pipe joint. Since the pipe is wrapped in insulation, the wrapping deterred the release of liquids to the surrounding soils. The pipeline was evacuated of hydrocarbons using fire water, and all liquids were evacuated from the pipeline using the on-site vacuum truck. All liquids removed from the pipeline were transferred to the on-site wastewater treatment plant. The line remains out-of-service until the repairs to the line are completed and the section of the pipeline is hydro-tested to ensure the integrity of the pipeline is sound.

Describe Area Affected and Cleanup Action Taken.*
Western contracted a hydro-excavator to hydro-excavate all soils around the leak area. A hydro excavator was the only safe method of excavation due to the fact that there exists additional power and product lines within the vicinity of where the leak occurred. A sufficient amount of soils were removed to be able to thoroughly assess an extended section of the pipeline. All hydro-excavated materials were transferred to secondary containment areas on-site for temporary storage. A sample was collected of the excavated materials for waste characterization and waste profile development. Initial preliminary lab results indicate that the excavated soils are non-hazardous. Western is scheduled to collect samples of the excavated area on Monday, June 4th, 2018. A representative from NMOCD-Aztec Office will be on-site to witness the sampling activities for closure.

A follow-up C-141 report will be submitted following the collection of the field samples and receipt of the waste characterization results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Kelly Robinson</i>		Approved by Environmental Specialist:	
Printed Name: <i>Kelly Robinson</i>		Approval Date:	Expiration Date:
Title: <i>Environmental Supervisor</i>		Conditions of Approval:	
E-mail Address: <i>Kelly.Robinson.Caudeaux</i>		Attached <input type="checkbox"/>	
Date: <i>6/1/18</i>	Phone: <i>505-632-4166</i>		

* Attach Additional Sheets If Necessary