

SRCC 97

FACSIMILE TRANSMITTAL



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6
1445 ROSS AVENUE
DALLAS, TEXAS 75202-2733

MULTIMEDIA PERMITTING AND PLANNING DIVISION
NEW MEXICO AND FEDERAL FACILITIES SECTION

PLEASE PRINT IN BLACK INK ONLY

TO: Dorinda Mancini, Environmental Manager, Giant Refining

MACHINE NUMBER: 505.721.0210

VERIFICATION NUMBER:

FROM: James A. Harris, Jr.
RCRA Facility Manager/Geologist

PHONE: (214) 665-8302

Mail Codes 6PD-N

OFFICE: New Mexico/Federal Facilities Section

PAGES, INCLUDING COVER SHEET
THREE (3)

DATE: February 6, 1997

PLEASE NUMBER ALL PAGES

INFORMATION FOR SENDING FACSIMILE MESSAGES

EQUIPMENT:

FACSIMILE NUMBER:

VERIFICATION NUMBER:

PANAFAX UF-766

(214) 665-6762

(214) 665-6760

COMMENTS

Dorinda,

FYI, please review. Let's try to go over this next week or at your convenience.

Thanx

JAMES

SWMU TRACKING LIST - GIANT REFINERY EPA ID: NMD000333211, Gallup, NM

| SWMU # now using 5/90 RFI WKPLN Designation; HSWA in (). | PHASE/GROUP | STATUS | COMMENTS/NOTES |
|---|-------------|-----------------------------------|---|
| 6: The Tank Farm - Leaded Gasoline Tanks (3) | Phase I | | Additional sampling for extent of contamination and confirmation sampling is required; completed first quarter '95 |
| 9: The Drainage Ditch near the Inactive Land Farm (10 & 13) | " | | Survey Plat submitted; closure certification must be submitted prior to initiating Class III Permit Mod process |
| 8: The Railroad Rack Lagoon (6) | " | under voluntary corrective action | monitoring requirements submitted w/quarterly status reports; notify EPA when final closure has been initiated; Survey Plat submitted; closure certification must be submitted prior to initiating Class III Permit Mod process |
| 8: The Overflow Ditch (associated w/Railroad Rack Lagoon) (6) | " | " | " |
| 8: The Fan Out Area (associated w/Railroad Rack Lagoon) (6) | " | " | " |
| 10: The Sludge Pits (9) | " | " | monitoring requirements submitted w/quarterly status reports; notify EPA when final closure has been initiated |

| | | | |
|--|-----------|---|---|
| 1: The Aeration Basin (1) | Phase II | soil and groundwater sampling every five years | RFI PHII RPT APP 1/94 w/modifications; Survey Plat submitted; closure certification must be submitted prior to initiating Class III Permit Mod process |
| 2: The Evaporation Ponds (2) | " | " | Survey and closure certification must be submitted prior to initiating Class III Permit Mod process |
| 12: Contact Waste Water Collection System (CWWCS) | " | Inspection every 5 years beginning 1996 | |
| 13: The Drainage Ditch between APIs Evaporation Ponds and the Neutralization Tank Evaporation Ponds (14) | " | soil and groundwater sampling every five years | Survey Plat submitted; closure certification must be submitted prior to initiating Class III Permit Mod process |
| 3: Empty Container Storage Area (5) | Phase III | | " |
| 4: Old Burn Pit (8) | " | | |
| 5: Landfill Areas (7) | " | a Voluntary Corrective Action (VCA) Plan to cap the "Landfill Areas" was submitted in March 1993. | EPA approved the VCA Plan on January 5, 1994 but required that additional soil borings be completed prior to Giant proceeding with the capping activities |
| 7: Fire Training Area (4) | " | Under VCA | |
| 11: Secondary Oil Skimmer (11) | " | Under VCA | discolored soil is the natural color; there is no hydrocarbon staining or odors detected; reference to "black fill" sand is actually "back fill" |