



Pic #1- Old HCL tank area- location of old monitor well OW20 had high PH readings.



Pic #4- Below-Grade Tank (BGT) old fuel oil unloading catch tank with steam trap.



Pic #2- water discharge to ground. Area located NE of plant gas concentration unit. PH of water was measured at 7



Pic #5- Fuel Oil Pump Basin



Pic # 3- Methanol drums in FCC area-need proper containment.



Pic #6- North side Fuel Oil Tank #706



Pic #9- Area between tanks 345,344 and 337.



Pic #7- FCC tank 703



Pic # 10- Railroad Rack Lagoon area.



Pic #8- Pipe Rack between Tank # 703 & 706 area free oil on ground.




Pic #11- Railroad Rack Lagoon landfarm area.



Pic #12 Contaminated spoils from fire training area and secondary oil skimmer (all non-hazardous).



Pic #15- Tank farm area- foreground shows current recovery well #5 (RW-5).



Pic #13- Old Temporary Emergency Pond far NW side of property.



Pic #14- Pond #11