


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505




Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Giant Refining Company - Ciniza	Contact Stephen C. Morris	
Address Route 3 Box 7 Gallup, NM 87301	Telephone No. 505-722-3833	
Facility Name Giant Refining Company - Ciniza Refinery	Facility Type Oil Refinery	
Surface Owner Giant Industries Inc.	Mineral Owner Giant Industries Inc.	Lease No.



LOCATION OF RELEASE

Unit Letter	Section 23 & 33	Township 15N	Range 15W	Feet from the	North/South Line	Feet from the	East/West Line	County McKinley
-------------	-----------------	--------------	-----------	---------------	------------------	---------------	----------------	-----------------

Latitude 35° 29' 30" Longitude 108° 24' 40"

NATURE OF RELEASE

Type of Release Slop Oil Release to lagoons and pond #1.	Volume of Release 800 gallons	Volume Recovered 700 gallons
Source of Release Oil/Water Separator	Date and Hour of Occurrence 3/3/07 0900hrs.	Date and Hour of Discovery 3/3/07 1000hrs.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell at OCD by phone.	
By Whom? Stephen C. Morris	Date and Hour 3/6/07 0930hrs.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The level device on the oil sump at the new API Separator failed to start the oil pump, allowing oil to pass through to the water pumps and out to the aeration lagoons and pond #1. Upon investigation, the pump switch was found to have been left in the off position rather than auto.		
Describe Area Affected and Cleanup Action Taken.* Aeration lagoons one and two and evaporation pond one were impacted by the oil release. Riley Industrial was contacted and two vacuum trucks were sent to work on the cleanup.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Stephen C. Morris</i>		OIL CONSERVATION DIVISION	
Printed Name: Stephen C. Morris		Approved by District Supervisor:	
Title: Environmental Engineer		Approval Date:	Expiration Date:
E-mail Address: smorris@giant.com		Conditions of Approval:	
Date: 03-12-2007 Phone: 505 722 0258		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary