



Certified Mail #7010 0290 0002 7735 3066

January 14, 2011

Mr. Carl Chavez Oil Conservation Division Environmental Bureau 1220 S. St. Francis Dr. Santa Fe, NM 87505

Re: OCD Discharge Permit GW-032 Condition 9

Dear Mr. Chavez:

Enclosed is the updated Gallup Refinery Storage Tank Table, which meets the requirement for an annual update as per Condition 9 of GW-032. This tank table shows progress on the tank gauging and containment projects for 2010.

In late 2008 Gallup purchased, installed and commissioned the wireless communication system by Honeywell. This system enables Gallup to bring level and other data from our outlying areas into our main Honeywell Distributed Control System (DCS). With the nine tanks complete in 2010 a total of 26 tanks have now been fitted with operational radar gauges and 2011 will be a very busy year with the planned installation of 11 additional gauges.

In 2010, four tanks were worked that did not require level gauges. The remaining tanks noted on the listing were inspected and had very minor repairs completed, coated as needed inside and outside and returned to service. Three of the nine gauge tanks were part of the new Stormwater/ Process Sewer system and include double flooring with leak detection between the floors. The two small ones (T-27 and T-28) were refurbished and the larger one (T-35) was built new. These were put into operation on 1/13/10. Other than these 3 tanks, Gallup did not install any new double floors in 2010.

Please contact me at (505) 722-0217 if you have any comments or questions regarding this submittal.

Sincerely

Ed Riege

Environmental Manager

C: Kristen Van Horn Mark B. Turri Don Riley