



Environmental Notification Tracking System

View Notification

[Back to list](#)

Notification Id 10343
 Notification Type Soil (pollution on or of the ground)
 Notification Date 7/19/2013 3:13:14 PM
 Notification Priority
 EJ Issue
 Status
 Assigned Bureau
 Assigned Staff
 Status Date
 Description Drain on Bay 3, the cement is eroded on the conduit leading into the drain. The erosion is around the middle of the conduit. The puddling fuel gets soaked into the ground.
 Location Western Refining, Jamestown.
 Nearest City Jamestown
 County Mckinley
 District
 Field Office
 Suspected Violator Western Refining
 Violator Address1
 Violator Address2
 Violator City Jamestown
 Violator State New Mexico
 Violator Zip
 Violator Phone
 Reporter Name Anonymous
 Reporter Address1

← Bay 3 needs to be ID'd

ENTERED

WESTERN REFINING Gallup
7/19/13