

VanHorn, Kristen, NMENV

From: Chavez, Carl J, EMNRD
Sent: Wednesday, June 28, 2017 8:51 AM
To: VanHorn, Kristen, NMENV
Subject: FW: RRR Gasoline Leak

Kristen:

Good morning.

FYI.

From: Chavez, Carl J, EMNRD
Sent: Wednesday, May 17, 2017 8:46 AM
To: 'Johnson, Cheryl' <Cheryl.Johnson@wnr.com>; VanHorn, Kristen, NMENV <Kristen.VanHorn@state.nm.us>; Smith, Cory, EMNRD <Cory.Smith@state.nm.us>; Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>
Cc: Hains, Allen <Allen.Hains@wnr.com>; Bailey, William <William.Bailey@wnr.com>
Subject: RE: RRR Gasoline Leak

Cheryl:

OCD notices that a C-141 Initial Form was not submitted to report the release.

OCD requests a map of the impacted area(s).

Thank you.

From: Johnson, Cheryl [<mailto:Cheryl.Johnson@wnr.com>]
Sent: Monday, May 8, 2017 3:04 PM
To: Chavez, Carl J, EMNRD <CarlJ.Chavez@state.nm.us>; VanHorn, Kristen, NMENV <Kristen.VanHorn@state.nm.us>; Smith, Cory, EMNRD <Cory.Smith@state.nm.us>
Cc: Hains, Allen <Allen.Hains@wnr.com>; Bailey, William <William.Bailey@wnr.com>
Subject: RRR Gasoline Leak

Carl, Kristen:

Just a follow -up on the gasoline spill that occurred yesterday. The spill was discovered at 8:00 AM when the rail loader noticed gasoline pooling under the pipe rack at the railroad rack (booster pump area) and flowing into a sewer box. Some gasoline spilled to ground surface but contained within the area into the sewer boxes. Offsites supervisor was immediately notified and Kurtz fire department was also called out as a precautionary measure. After lowering level in the sewer box, it was discovered that a ¾" valve was in the open position on the DGS 105 additive tank. A total of 3 loads was vacuumed out of the sewer boxes - with an estimated total of 8900 gallons of 89 Octane recovered via vacuum truck. Clean up continues in this area.

No personal injuries and no fires reported with this incident.

Date of Incident: May 7, 2017

Discovered: 8:00AM

Area: RRR Booster pump area

Source: 3/4" valve off of the DGS additive tank system

Weather Conditions: Breezy, clear to partly cloudy

Checked wind conditions at 11:30am: 14mph SE (10 min average = 15 mph)

Latitude: 35°29'28.56" N

Longitude: 108°25'24.24"W

If you have any questions or require further information please contact Mr. Bill Bailey,
Environmental Supervisor (505) 726-9743.

cj

Cheryl Johnson
Environmental Specialist

Western Refining - Gallup Refinery
92 Giant Crossing Road
Gallup, NM 87301
505 722 0231 Direct
505 863-0930 Fax
505 722 3833 Main
cheryl.johnson@wnr.com