zia engineering & environmental consultants, inc
755 S. Telshor Blvd. Ste. F-201
Las Cruces, NM 88011
575-532-1626 p
575-532-1587 f

CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

PROJECT NO.

PROJECT NAME: Rhodes Canyon

SAMPLER'S SIGNATURE: Brady T. Davis

DATE	TIME	SAMPLE ID	MATRIX	LAB NO.	NO. OF CONTAINERS	Total Pb	GRO	VOCs	SVOCs	Alkalinity	pH	TDS	Sulfate			REMARKS
8-21-12	1150	RCRC-0114-RMW-001-0812	Water		10	X	X	X	X	X	X	X	X			
8-21-12	1150	RCRC-0114-RMW-001-ms/msd	Water		10	X	X	X	X	X	X	X	X			matrix Spike/duplicate
8-21-12	1310	RCRC-0114-RMW-003-0812	Water		10	X	X	X	X	X	X	X	X			
8-21-12	1415	RCRC-0114-RMW-006-0812	Water		10	X	X	X	X	X	X	X	X			
8-21-12	1415	RCRC-0114-RMW-006-TB	Water		2			X								trip Blank

PROJECT INFORMATION	SAMPLES RECEIVED	1. RELINQUISHED BY: (SIGNATURE)	2. RELINQUISHED BY: (SIGNATURE)	3. RECEIVED BY LAB: (SIGNATURE)
PROJECT MANAGER: Brad Davis	TOTAL NO. OF CONTAINERS	(PRINTED NAME) Bradley T. Davis	(PRINTED NAME)	(PRINTED NAME)
SHIPPING ID NO.	CHAIN OF CUSTODY SEALS	RECEIVED BY: (SIGNATURE)	RECEIVED BY: (SIGNATURE)	(COMPANY)
	GOOD CONDITION/CHILLED	(TIME/ DATE)	(TIME/ DATE)	(TIME/ DATE)
VIA: Fed EX	CONFORMS TO RECORD	SPECIAL INSTRUCTIONS / COMMENTS:		

PLEASE USE BALL POINT PEN

DISTRIBUTION: WHITE - PROJECT FILES; YELLOW - LAB; PINK - FIELD COPY

From: (505) 532-1526
Z a Engineering

755 S Telshor Blvd.
Suite Q-201
Las Cruces, NM 88011

Origin ID: LRUA

FedEx Express

Ship Date: 21AUG12
ActWgt: 65.0 LB
CAD: 102287640/INET3300

Delivery Address Bar Code

SHIP TO: (512) 388-8222
BILL SENDER

John Dupont
DHL Analytical
2300 DOUBLE CREEK DR

ROUND ROCK, TX 78664

Ref # Brad
Invoice #
PO # FWSE-09-015 Task 035
Dept #

WED - 22 AUG A1
PRIORITY OVERNIGHT

TRK# 7987 9460 7480
0201

78664
TX-US
AUS

XH BSMA

IF S

AL

TODY SEA

8-21-12
Bradley T. Davis

EAL
OKEN

QEC
Quality Environmental Containers
800-255-3950 • 304-255-3900

IF S
IS BR
IECK
ORE

DHL Analytical

Sample Receipt Checklist

Client Name Zia Engineering & Environmental

Date Received: 8/22/2012

Work Order Number 1208206

Received by JB

Checklist completed by: [signature] Signature 8/22/2012 Date

Reviewed by [initials] Initials 8/22/2012 Date

Carrier name: FedEx 1day

Shipping container/cooler in good condition?	Yes ☑	No ☐	Not Present ☐
Custody seals intact on shippping container/cooler?	Yes ☑	No ☐	Not Present ☐
Custody seals intact on sample bottles?	Yes ☐	No ☐	Not Present ☑
Chain of custody present?	Yes ☑	No ☐	
Chain of custody signed when relinquished and received?	Yes ☑	No ☐	
Chain of custody agrees with sample labels?	Yes ☑	No ☐	
Samples in proper container/bottle?	Yes ☑	No ☐	
Sample containers intact?	Yes ☑	No ☐	
Sufficient sample volume for indicated test?	Yes ☑	No ☐	
All samples received within holding time?	Yes ☑	No ☐	
Container/Temp Blank temperature in compliance?	Yes ☑	No ☐	3.1 °C
Water - VOA vials have zero headspace?	Yes ☑	No ☐	No VOA vials submitted ☐
Water - pH acceptable upon receipt?	Yes ☑	No ☐	Not Applicable ☐

Adjusted? no Checked by [initials]

Any No response must be detailed in the comments section below.

Client contacted _____ Date contacted: _____ Person contacted _____

Contacted by: _____ Regarding: _____

Comments: _____

Corrective Action _____

Page 1 of 1